

TMT IRMOS Work Breakdown Structure (WBS)

R. Dekany
2/7/2006

Principles invoked here:

Organize WBS in a way that facilitates I&T (e.g. consider MOAO as a work package)

Most motion control handled by the MOAO Supervisory Controller

Convention is to use 5 letter abbreviations for software deliverables

WBS **WBS**
Level **Number**

Title

4	TMT.INS.INST.IRMOS	IRMOS
5	TMT.INS.INST.IRMOS.MAN	IRMOS Management
5	TMT.INS.INST.IRMOS.SYS	IRMOS Systems Engineering
5	TMT.INS.INST.IRMOS.RLAY	IRMOS Offner Relay
5	TMT.INS.INST.IRMOS.MOAO	IRMOS MOAO
5	TMT.INS.INST.IRMOS.OSM	IRMOS Object Selection Mechanism
5	TMT.INS.INST.IRMOS.SPEC	IRMOS Spectrograph
5	TMT.INS.INST.IRMOS.AMS	IRMOS Acquisition and Metrology System
5	TMT.INS.INST.IRMOS.STIM	IRMOS Stimulus
5	TMT.INS.INST.IRMOS.IROT	IRMOS Instrument Rotator
5	TMT.INS.INST.IRMOS.IT	IRMOS System Integration and Testing
5	TMT.INS.INST.IRMOS.COMM	IRMOS Commissioning